


COPY OF PAPERS
ORIGINALLY FILED

Attorney Docket No.: 042390.P7092

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE



In re application of:

Mann, et al.

Application No: 09/409,627

Filed: September 30, 1999

For: METHOD AND APPARATUS FOR
DYNAMIC UNATTENDED NETWORK
CONFIGURATION OF AN
ALERT-BASED CLIENT

Examiner: K. Parton

Art Unit: 2153

Assistant Commissioner For Patents
Washington, D.C. 20231

REQUEST TO APPROVE DRAWING CHANGES

Dear Sir:

Enclosed is a photocopy of FIG. 2 and FIG. 6 with changes marked in red ink. A duplicate copy is provided. FIG. 2 has been amended so that one reference numeral does not point to two objects. FIG. 6 has been amended so that the reference numerals are consistent with the specification. Applicants respectfully request that the proposed changes in FIG. 2 and FIG. 6 be approved by the Examiner.

Respectfully submitted,
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN, LLP

Date: 11 July 2002

Philip A. Pedigo
Philip A. Pedigo
Attorney for Applicant
Reg. No. P-52,107

12400 Wilshire Boulevard
Seventh Floor
Los Angeles, CA 90025-1026
(503) 684-6200

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail with sufficient postage in an envelope addressed to the Commissioner of Patents, Washington, D.C. 20231 etc

11 July 2002
Date of Deposit
DEBORAH L. HUGHES
Name of Person Mailing Correspondence
SOLO 7/11/02
Signature Date




FIGURE 2




FIGURE 2

Figure 6A

610 → [FUNCTION_LIST]
 0 = 20000;21015
 1 = 20001;21016
616 → 2 = 20002;21017

620 → [FUNCTION_MAP]
~~622~~ ~~631~~ → COMPANYXYZ = 1,1;2,2;3,3;4,4;5,5;9,6

630 → [SUBFUNCTIONS_2]
632 → 0 = 16001;16002
634 → 1 = 16003;16004

 [COMPANYXYZ]
 DeviceType = 0
 StatusPolarity = 0xD9
 StatusPowerupMask = 0x1B
 StatusPowerdownMask = 0x19

 [CompanyXYZ]
652 → 101 I:300401
 110 W:300402
 114 C:300403

 [CompanyABC]
662 → 101 300402;300800;300801
 110 300405

Figure 6B

672 → 300401 300402 300403 300800 300801	A failure occurred during testing of the system board A memory parity failure occurred Adapter ROM failure Memory may be defective Replace memory
---	---

Figure 6A

610 → [FUNCTION_LIST]
 0 = 20000;21015
 1 = 20001;21016
616 → 2 = 20002;21017

620 → [FUNCTION_MAP]
622/621 → COMPANYXYZ = 1,1;2,2;3,3;4,4;5,5;9,6

630 → [SUBFUNCTIONS_2]
632 → 0 = 16001;16002
634 → 1 = 16003;16004

 [COMPANYXYZ]
 DeviceType = 0
 StatusPolarity = 0xD9
 StatusPowerupMask = 0x1B
 StatusPowerdownMask = 0x19

 [CompanyXYZ]
652 → 101 I:300401
 110 W:300402
 114 C:300403

 [CompanyABC]
662 → 101 300402;300800;300801
 110 300405

Figure 6B

672 → 300401 300402 300403 300800 300801	A failure occurred during testing of the system board A memory parity failure occurred Adapter ROM failure Memory may be defective Replace memory
---	---